

## **POSITION: OSP - Underground General Laborer**

*The Underground General Laborer will be responsible for placing conduit and/or cables in trenches, splice conduit. They will assist skilled trade people and perform general labor duties at various pipeline project sites.*

### **Responsibilities:**

- Move drilling equipment to the right location by driving or controlling the load and upload.
- Assist in set up of drilling machine by connecting drill pipe sections, etc.
- Connect power cables or hoses for water and air supply.
- Operate slush pumps to ensure circulation and consistency of drilling fluid or mud in well.
- Assist to correct problems in drilled holes caused by mechanical breakdowns or by harmful natural conditions.
- Operate locator to track Bore Head while drilling.
- Locate and recover lost or broken bits, casings or drill pipes from wells using special tools.
- Dig or set up pits by hand if necessary.
- Fill water storage tank daily.
- Break down and cleanup equipment after completion of each job.
- Fill in and restore grounds to original conditions.

### **Qualifications:**

- 1-year experience in OSP construction
- Experience using hand and power tools.
- Attend company provided training.
- Basic construction knowledge.
- Able to frequently stand, walk, sit, use hands to finger/handle/feel, reach with hands and arms, talk or hear
- Able to climb or balance, stoop, kneel, crouch or crawl.
- Able to lift or carry up to 10 or 25 lbs. and occasionally up to 50 or 100 lbs.
- Able to work outside in all weather conditions.
- Able to travel to job sites as needed.
- Must pass a background check, drug test, and motor vehicle check
- Must possess a valid driver's license.

If interested in this position, please apply through the TERO office or submit a resume to Megan Peterson at [mpeterson@mc-ec.org](mailto:mpeterson@mc-ec.org).