Daycare – Existing Photo References

Exterior Photos

Ref A – East Wing Main Entry



Ref B – East Wing



Ref C – East Wing



Ref D – West Wing



Ref E – Typ Light



Ref F – West Wing Entry



Ref G – Typ Light



Ref H – Breezeway Column




Ref J - Breezeway soffit



Ref K – Trip Hazard



Ref L – Wooden Fence



Ref M – Wooden Fence




Ref N – Trip Hazard



Ref O – Existing Gate and Exit Ramp



Ref P – Sinking Lawn



Ref Q – Sinking Stair



Ref R – Existing Gutter Conditions



Ref S – Playshed




Ref T – Toddler Play Area




Interior Photos

Ref AA – Ceiling Condition



Ref BB – Ceiling Condition



Ref CC – Exhaust Fan




Ref DD – Floor Condition




Ref EE – Typical Wall Condition



Ref FF – Kid Size Toilet



Ref GG –Toilet (access panel behind toilet)



Ref HH – Toilet Partitions / Missing Door



Ref JJ – Bathroom Vanity



Ref KK – Faucet in Kitchen



Ref LL – Kitchen Sink



Ref MM – Sink in casework



Ref NN – Sink in casework



Ref OO – Exterior Door



Ref PP – Exterior Door



Ref QQ – Exterior Door



Ref RR – Interior Door



Ref SS – Interior Door in Panel Wall



Ref TT – Interior Door in Panel Wall

